

Actual Health and Safety Equipment Maintenance Map for St Columba's United Reformed Church, Oxford.

Version 0.1 September 2009. (There is also a Fire Equipment Maintenance Map.)

ACM, ACM(e)	Asbestos Containing Material (external)
NO	No admittance
LOC	Keep locked
FA	First Aid box and sign
DGR	Danger Flammables
SU	Sink usage notices
KN	Sharp knives reminder
FS	Food safety poster
PP	Mandatory Health and Safety Poster
WR	Wheelchair ramp and sign
FR	Fridge Hygiene reminder
DB	Dishwasher/ hazardous cleaning Substance location poster
X	Attention alarms (red cord)
HAZ	Working with Hazardous Substances
A	Noticeboard for public notices as Follows: Employer's Liability, Public Liability Insurance, Candle Use, Health and Safety Statement, Fire Equipment Test certificate, Lone worker's guidance, Stewarding notes, lost property exemption.
SL	Slippery floor sign
CT	Temp. sign about stacking/using chairs and tables
	Trip Hazard strips painted (balcony = tape, not painted)
Ext	Location of mop, bucket, gloves for whoever does External cleaning (porch) on Sundays
Sc!	Danger of scalding
000	Chain mounts for church open signs
PPE	Face masks, gloves, dispensing pouch
///	Ladder use poster
@	Baby changing bench, nappy disposal bags (keep stocked)
&	Disabled user toilet with descending arm rests, mirror, easy access sink

